

Table of Contents

Table of Contents	1
Report of Discharge (CSO\SSO\RTB)	2
(Submission #: HPG-YDD3-AT1HZ, version 1)	2
Details	2
Form Input	2
Report Details	2
Discharge Details (1 of 1)	2
SSO Discharge from 1870 East Lake Mitchell Drive - Force Main`OUTFL_ID_TXT`	2
Additional Details	4
Status History	4

Report of Discharge (CSO\SSO\RTB)

version 1.14

(Submission #: HPG-YDD3-AT1HZ, version 1)

Details

Submission ID HPG-YDD3-AT1HZ

Status Submitting

Form Input

Report Details

Is this the initial or final discharge report?

Initial

Site/Facility Name:

Lake Mitchell Sewer Authority (former Wexford Co DPW) CM

Permit Number (if applicable):

NONE PROVIDED

Sewer System or Treatment Facility Owner

Organization Name

Lake Mitchell Sewer Authority

Phone Type	Number	Extension
------------	--------	-----------

Business	2317750155	
----------	------------	--

Email

operationsoffice@lakemitchellsewer.com

Fax

2317750156

Address

3161 South Lake Mitchell Drive

Cadillac, MI 49601

United States

Facility Address

3161 South Lake Mitchell Drive

Cadillac, MI 49601

Sewer System or Treatment Facility Owner Location

44.2298,-85.5088

3161 South Lake Mitchell Drive, Cadillac, MI

Discharge Details (1 of 1)

SSO Discharge from 1870 East Lake Mitchell Drive - Force Main`OUTFL_ID_TXT`

Discharge Type:

SSO Discharge

SSO Discharge

The reported discharge is from a private or municipal separate sewer collection system (not a wastewater treatment plant) during wet or dry weather, or a dry weather discharge from a municipal combined sewer collection system.

Is the outfall or discharge area located at a private residential address?

NO

Outfall or Discharge Area Name

1870 East Lake Mitchell Drive - Force Main

Outfall or Discharge Area Description

Cracked 6" Force Main

Outfall or Discharge Area Location

44.26187729999999,-85.47178760000001

Has the discharge ended?

YES

Volume Discharged	Unit	Was the volume estimated?
1350	Gallons	Yes

Quality of Discharge

Raw Sewage

Please describe the discharge, including the reason for Discharge

Contractors were on site to make a repair to a broken discharge line on grinder pump station 32B. When installing the steel piling, it cracked the side of the 6" force main. Staff had two septic haulers on site to pump and haul the up stream flow from lift station 2B and the grinder pumps in between.

Was the land or surface water impacted by the discharge?

Land impacted only

Name/description of the land impacted:

Soil in the excavated area

Discharge Event Start

Date	Time
4/14/2022	01:30 pm

Discharge Event End

Date	Time
4/14/2022	02:30 pm

Initial Notification

Organization	Date	Time
Local Health Department	4/14/2022	07:00 pm
Daily Local Newspaper	4/14/2022	07:00 pm

Was EGLE notified prior to this report being received?

EGLE was notified prior to this report being submitted

Prior EGLE notification that discharge has started

EGLE Notification Method	Person(s) notified	EGLE Notification Date	EGLE Notification Time	Comments
Phone	Donal Brady	4/14/2022	03:50 pm	NONE PROVIDED

Notification that discharge has concluded.

Organization	Date	Time
Local Health Department	4/14/2022	07:00 pm
Daily Local Newspaper	4/14/2022	07:00 pm

Precipitation Type(s) (Select none if there was no precipitation)

None

Additional Details

Report Submitter

Prefix

Ms.

First Name

Sheila

Last Name

Hill

Title

Project Manager

Organization Name

Lake Mitchell Sewer Authority

Phone Type

Business

Number

2317750155

Extension

Email

operationsoffice@lakemithcellsewer.com

Fax

NONE PROVIDED

Address

3161 S LAKE MITCHELL DR

CADILLAC, MI 49601

United States

Do you have any additional comments or uploads you would like to provide?

NO

Status History

	User	Processing Status
4/14/2022 7:05:34 PM	Sheila Hill	Draft
4/14/2022 7:15:31 PM	Sheila Hill	Submitting