

# Table of Contents

Table of Contents	1
Report of Discharge (CSO\SSO\RTB)	2
(Submission #: HPG-VZNH-SJ8TP, version 1)	2
Details	2
Form Input	2
Report Details	2
Discharge Details (1 of 1)	2
SSO Discharge from 32B Grinder Pump Station`OUTFL_ID_TXT`	2
Additional Details	4
Attachments	4
Status History	5

# Report of Discharge (CSO\SSO\RTB)

version 1.14

(Submission #: HPG-VZNH-SJ8TP, version 1)

## Details

---

**Submission ID** HPG-VZNH-SJ8TP

**Status** In Process

## Form Input

---

### Report Details

**Is this the initial or final discharge report?**

Initial

**Site/Facility Name:**

Lake Mitchell Sewer Authority (former Wexford Co DPW) CM

**Permit Number (if applicable):**

NONE PROVIDED

**Sewer System or Treatment Facility Owner**

**Organization Name**

*Lake Mitchell Sewer Authority*

**Phone Type    Number    Extension**

Business        2317750155

**Email**

operationsoffice@lakemitchellsewer.com

**Fax**

2317750156

**Address**

3161 South Lake Mitchell Drive

Cadillac, MI 49601

United States

**Facility Address**

3161 South Lake Mitchell Drive

Cadillac, MI 49601

**Sewer System or Treatment Facility Owner Location**

44.2298,-85.5088

3161 South Lake Mitchell Drive, Cadillac, MI

### Discharge Details (1 of 1)

**SSO Discharge from 32B Grinder Pump Station`OUTFL\_ID\_TXT`**

**Discharge Type:**

SSO Discharge

**SSO Discharge**

The reported discharge is from a private or municipal separate sewer collection system (not a wastewater treatment plant) during wet or dry weather, or a dry weather discharge from a municipal combined sewer collection system.

**Is the outfall or discharge area located at a private residential address?**

NO

**Outfall or Discharge Area Name**

32B Grinder Pump Station

**Outfall or Discharge Area Description**

Surrounding soil and edge of road

**Outfall or Discharge Area Location**

44.26187729999999,-85.47178760000001

**Has the discharge ended?**

YES

Volume Discharged	Unit	Was the volume estimated?
250	Gallons	Yes

**Quality of Discharge**

Raw Sewage

**Please describe the discharge, including the reason for Discharge**

On Monday, April 11, 2022, LMSA staff received a call from a customer notifying them of a possible SSO. The customer indicated that the neighbor told them the station had been overflowing over the weekend. This person reported it as soon as they were made aware. It should be mentioned that no one reported the SSO over the weekend. Staff was unable to get an exact confirmation of the station of the discharge. The date start will be at the time of notification of the SSO. The station has a broken discharge line and will require emergency repair. The repair work is scheduled to begin on April 13th. The station was immediately shut down to prevent further overflow. The wastewater will be pumped and hauled in the interim.

**Was the land or surface water impacted by the discharge?**

Land impacted only

**Name/description of the land impacted:**

Adjacent area next to the grinder station and side of road

**Discharge Event Start**

Date	Time
4/11/2022	10:00 am

**Discharge Event End**

Date	Time
4/11/2022	10:20 am

**Initial Notification**

Organization	Date	Time
Local Health Department	4/11/2022	04:40 pm
Daily Local Newspaper	4/11/2022	04:40 pm

**Was EGLE notified prior to this report being received?**

EGLE was notified prior to this report being submitted

**Prior EGLE notification that discharge has started**

EGLE Notification Method	Person(s) notified	EGLE Notification Date	EGLE Notification Time	Comments
Phone	Donal Brady	4/11/2022	04:13 pm	NONE PROVIDED

**Notification that discharge has concluded.**

Organization	Date	Time
Local Health Department	4/11/2022	04:40 pm
Daily Local Newspaper	4/11/2022	04:40 pm

**Precipitation Type(s) (Select none if there was no precipitation)**

None

**Additional Details**

**Report Submitter**

**Prefix**

Ms.

**First Name**

Sheila

**Last Name**

Hill

**Title**

Project Manager

**Organization Name**

Lake Mitchell Sewer Authority

**Phone Type**

Business

**Number**

2317750155

**Extension**

**Email**

operationsoffice@lakemithcellsewer.com

**Fax**

NONE PROVIDED

**Address**

3161 S LAKE MITCHELL DR

CADILLAC, MI 49601

United States

**Do you have any additional comments or uploads you would like to provide?**

YES

**Additional Information**

As a precautionary measure, the area was broadcast with lime and taped off to prevent public access. It should be noted, that the grinder pump stations have emergency phone number to call in the event of an alarm or sewer emergency. This information is also provided to public via monthly sewer bills, it is posted on the LMSA website, and on LMSA's answering system.

**Upload additional information, as needed.**

[image000000.jpg - 04/11/2022 05:19 PM](#)

[image32B.jpg - 04/11/2022 05:19 PM](#)

**Comment**

NONE PROVIDED

**Attachments**

Date	Attachment Name	Context	User
4/11/2022 5:19 PM	image000000.jpg	Attachment	Sheila Hill
4/11/2022 5:19 PM	image32B.jpg	Attachment	Sheila Hill

## Status History

---

	User	Processing Status
4/11/2022 4:53:55 PM	Sheila Hill	Draft
4/11/2022 5:30:10 PM	Sheila Hill	Submitting
4/11/2022 5:30:17 PM	Sheila Hill	Submitted
4/11/2022 5:30:22 PM	Sheila Hill	In Process