

Table of Contents

Table of Contents	1
Report of Discharge (CSO\SSO\RTB)	2
(Submission #: HPA-W3R2-VCJ87, version 1)	2
Details	2
Form Input	2
Report Details	2
Discharge Details (1 of 1)	2
SSO Discharge from Lift Station 1B	2
Additional Details	4
Status History	4

Report of Discharge (CSO\SSO\RTB)

version 1.14

(Submission #: HPA-W3R2-VCJ87, version 1)

Details

Submission ID HPA-W3R2-VCJ87

Status Submitting

Form Input

Report Details

Is this the initial or final discharge report?

Initial

Site/Facility Name:

Lake Mitchell Sewer Authority (former Wexford Co DPW) CM

Permit Number (if applicable):

NONE PROVIDED

Sewer System or Treatment Facility Owner

Organization Name

Lake Mitchell Sewer Authority

Phone Type **Number** **Extension**

Business 2317750155

Email

operationsoffice@lakemitchellsewer.com

Fax

2317750156

Address

3161 South Lake Mitchell Drive

Cadillac, MI 49601

United States

Facility Address

3161 South Lake Mitchell Drive

Cadillac, MI 49601

Sewer System or Treatment Facility Owner Location

44.2298,-85.5088

3161 South Lake Mitchell Drive, Cadillac, MI

Discharge Details (1 of 1)

SSO Discharge from Lift Station 1B

Discharge Type:

SSO Discharge

SSO Discharge

The reported discharge is from a private or municipal separate sewer collection system (not a wastewater treatment plant) during wet or dry weather, or a dry weather discharge from a municipal combined sewer collection system.

Is the outfall or discharge area located at a private residential address?

NO

Outfall or Discharge Area Name

Lift Station 1B

Outfall or Discharge Area Description

Lift Station 1B

Outfall or Discharge Area Location

44.2592838,-85.4688096

Has the discharge ended?

YES

Volume Discharged	Unit	Was the volume estimated?
300	Gallons	Yes

Quality of Discharge

Diluted Raw Sewage

Please describe the discharge, including the reason for Discharge

The Operation & Maintenance Technician responded to a high water alarm at SPS 1B at 1:50 a.m. on August 10, 2021. Upon arrival at 2:25 a.m, the Technician observed the station discharging. The discharge ended approximately 5 minutes after the Technicians arrival. The discharge event occurred due to the heavy rainfall in a short period of times, approximately 3-4" of precipitation. The major factor is sump pumps and roof/foundation drains that are illegally connected to the sewer system. There was very little debris on the ground.

Was the land or surface water impacted by the discharge?

Both land and water impacted

Name of Surface Water(s) Impacted:
Swamp wetlands directly East of the lift station

Name/description of the land impacted:

Area directly adjacent to the lift station

Discharge Event Start

Date	Time
8/10/2021	02:15 am

Discharge Event End

Date	Time
8/10/2021	02:30 am

Initial Notification

Organization	Date	Time
Local Health Department	8/10/2021	12:43 pm
Daily Local Newspaper	8/10/2021	01:10 pm

Was EGLE notified prior to this report being received?

This report is being used as the initial notification to EGLE

Notification that discharge has concluded.

Organization	Date	Time
Local Health Department	8/10/2021	12:43 pm
Daily Local Newspaper	8/10/2021	01:10 pm

Precipitation Type(s) (Select none if there was no precipitation)

Rain

Has the precipitation ended?

YES

Precipitation

Start Date	Start Time
8/9/2021	09:00 pm

Precipitation Amount (Inches)	Precipitation End Date	Precipitation End Time
3.5	8/10/2021	03:00 am

Precipitation comments

Heavy rainfall in short period of time

Was this discharge disinfected to meet fecal coliform limitations?

NO

Additional Details

Report Submitter

Prefix

Ms.

First Name

Sheila

Last Name

Hill

Title

Project Manager

Organization Name

Lake Mitchell Sewer Authority

Phone Type

Business

Number

2317750155

Extension

Email

operationsoffice@lakemithcellsewer.com

Fax

NONE PROVIDED

Address

3161 S LAKE MITCHELL DR

CADILLAC, MI 49601

United States

Do you have any additional comments or uploads you would like to provide?

NO

Status History

	User	Processing Status
8/10/2021 12:43:49 PM	Sheila Hill	Draft
8/10/2021 3:35:31 PM	Sheila Hill	Submitting

	User	Processing Status
8/10/2021 3:35:47 PM	Sheila Hill	Submitted